DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-019736 Address: 333 Burma Road **Date Inspected:** 17-Jan-2011

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Oiu Wen. **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

OBG components.

Bridge No: 34-0006 **Component:**

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Mr. Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA Inspector observed and/or found the following:

Bay 14:

Notification no: 008203.

OBG Seg 13CW:

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector has generated MT report for this date. The members are identified as OBG components. The weld designations MT inspected are as follows:

- 1) FB3220-001- 122 to 125, 130 to 133, 139, 140, 145, 146, 148, 149.
- 2) SEG3015K- 022, 023.

Notification no: 008201.

OBG Seg 13CW:

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA inspector performed MT of approximately 15% of an area that has been previously tested and accepted by ZPMC QC personnel. This QA Inspector has generated MT report for this date. The members are identified as OBG components. The weld designations MT inspected are as follows:

- 1) SEG3015N-044 to 056.
- 2) LD3036-001-201~204, 230, 231, 257, 258, 287, 288, 317, 318.

This QA Inspector observed the following work in progress:

OBG Seg 13CW

The Submerged Arc Welding (SAW) process on weld joint no: SEG3015-001 [Deck Panel (DP) 3148A to DP3149A, complete joint penetration (CJP) weld]. The welder is identified as 250050 and was observed welding in the 1G position. ZPMC QC was identified as Mr. Zhang Lin. The welding variables recorded by QC appeared to comply with WPS: B-T-223(2)1T-ESAB-1.

OBG Seg 13AW:

Repair welding of weld joint no: SEG3013P-275 [Edge Beam (EB) 3045B to Floor Beam (FB) 3176A, CJP weld at panel point (PP) 118]. The welder is identified as 067183 and was observed welding in the 4G position. Welding process was identified as Shielded Metal Arc Welding (SMAW). ZPMC QC was identified as Liu Feng. The welding variables recorded by this QC appeared to comply with WPS: 345-SMAW-4G(4F)-FCM-Repair. Repair welding was done as per Welding Repair Report (WRR): B-WR 19920 Rev-0.

Repair welding of weld joint no: SEG3013AK-124 (EB3049A to FB3184A, CJP weld at PP119). The welder is identified as 066236 and was observed welding in the 2G position. Welding process was identified as Flux Cored Arc Welding (FCAW). ZPMC QC was identified as Liu Feng. The welding variables recorded by this QC appeared to comply with WPS: 345-FCAW-2G(2F)-FCM-Repair. Repair welding was done as per WRR: B-WR 19913 Rev-0.

OBG Seg 14W:

Repair welding of weld joint no: SEG3020X-008 [FB3327A to Longitudinal Diaphragm (LD) 3051A, CJP weld at PP127]. The welder is identified as 051348 and was observed welding in the 3G position. Welding process was identified as SMAW. ZPMC QC was identified as Mr. Zhu Lin. The welding variables recorded by this QC appeared to comply with WPS: 345-SMAW-3G(3F)-FCM-Repair. Repair welding was done as per WRR: B-WR 20152 Rev-0.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No significant conversations were reported on this date.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372., who represents the Office of Structural Materials for your project.

Inspected By:	Wadkar,Sailesh	Quality Assurance Inspector
Reviewed By:	Patterson,Rodney	QA Reviewer